

# MOUNTING INSTRUCTIONS FOR RG6/59 MINI-ALM-UNIV-EPA



Step 1

## Step 1.

We strongly recommend the use of Corning Cabelcon's pre-adjusted Rotary Cable Stripper for proper preparation of the cable. Please read the instructions for use, supplied with the tool.

Stripping dimensions

A = 6.5 mm. B = 6.5 mm.

If the inner conductor is too long, then cut it down to a length of 6.5 mm. You can use the rings as a cutting guide (shown left).

Do not cut the braid or mark center conductor.

## Step 2.

Fold exposed braid back over jacket.

For "Quad shield", "Tri shield" and "Super shield" cables: Remove the outer braid and foil only. Fold back the braid over the jacket and leave the foil attached to the dielectric.

## Step 3.

Press the front part of the connector (with the built-in "tool") against the cable and turn slowly to prepare the foil to enter into the connector.

## Step 4.

Push the connector over the foil and allow the support mandrel to slide between the foil and braid.


A mounting tool for F connector and a rubber tool for cable support can be used to keep a better grip on the connector and cable during installation [F]. Press and turn until the dielectric is flush with the support mandrel face [G].

## Step 5.

Crimp the connector using the proper crimping tool.

## Step 6.

Mount the connector into the tap. We recommend to tighten the nut with a torque of 4,5 Nm to ensure optimal performance of your network.



Recommended tools	Item no.
Rotary Cable Stripper	98501010
Rubber tool for cable support	98028785
Mounting tool for F connector	98028805
Crimp tool MINI/ALM	98028820
Crimp tool ALM/UNIV/EPA	98028840
Crimp tool ALM /RG11	98028830
Torque Wrench AH (angle head) HEX mm 4,5 Nm	98029080

ISO 9001 certified

Distributor:

**CABELCON**  
connectors

Corning Cabelcon ApS, Industriparken 10, DK 4760 Vordingborg  
Tel: +45 55 98 55 99 · Fax: + 45 55 98 55 04  
E-mail: cabelcon@cabelcon.dk · www.cabelcon.dk